

Sample Vehicle Auto Scan & Create DTC Report – G scan 3



System Search

System	DTC
PCM(Powertrain Control Module)	PM 05:13 0
★PATS(Passive anti theft system)-Beta	PM 05:13 -
★ABS(Anti-Lock Brake System)	PM 05:13 0
IC(Instrument Cluster)	PM 05:13 1
★EPS(Electronic-Controlled Power Steering)	PM 05:13

G-SCAN

Connecting. Please wait a moment. (5/10)

!!!! Symbol Notice !!!!

[0] No DTC is found in the system.

[-] System does not support DTC reading.

[->] Select from the system menu individually.

START STOP ★ LIST RESTART

Copy right G-Scan Oceania

System Search

System	DTC
PCM(Powertrain Control Module)	PM 05:13 0
★PATS(Passive anti theft system)-Beta	PM 05:13 -
★ABS(Anti-Lock Brake System)	PM 05:13 0
IC(Instrument Cluster)	PM 05:13 1
★EPS(Electronic-Controlled Power Steering)	PM 05:13 0
BCM/GEM(Body Control Module/Generic Electronic Module)	PM 05:14 0
★RCM(Restraint Control Module)	PM 05:14 0
★Without SKE	PM 05:14 1

START STOP ★ LIST SHOW DTC RESTART

Copy right G-Scan Oceania

System Search

DTC	State
* IC(Instrument Cluster)	
-> U042092 Invalid Data Received From (PSCM)	Not Present
* Without SKE	
-> U042092 Invalid Data Received From (PSCM)	Not Present

REPORT BACK


Copy right
G-Scan Oceania

Diagnostic Report

+ Create New Report

SUBARU Jul-11-2018 03:41:18	International(2002 - Present)/16PIN CONNECTOR CustomerName --- VIN --- LicensePlate ---	Pre-repair Scan Result Not Saved ADD	Post-repair Scan Result Not Saved ADD	Comment / Attachment Not Saved Edit
DEMO SOFTWARE Jul-11-2018 02:47:46	Test CustomerName test VIN test LicensePlate test	Pre-repair Scan Result Jul-11-2018 14:47:44 Overwrite	Post-repair Scan Result Jul-11-2018 14:50:21 Overwrite	Comment / Attachment Not Saved Edit
MAZDA Jan-13-2019 04:41:38	International/DEMIO/VERISA/MAZDA2/1.5L ZY CustomerName test VIN JM0DE10Y1A0152283 LicensePlate abc123	Pre-repair Scan Result Jan-13-2019 16:44:38 Overwrite	Post-repair Scan Result Jan-13-2019 16:44:38 Overwrite	Comment / Attachment Jan-13-2019 16:44:50 Edit

Copy right
G-Scan Oceania



Gscan | Diagnostic Report

Jan-13-2019 04:41:38
RAG00107

workshop
1a Street Australia
joe

CustomerName test

Vehicle Information

MAZDA/International/DEMIO/VERISA/MAZDA2/1.5L ZY

VIN JM0DE10Y1A0152283 ModelYear 2008
LicensePlate abc123 Odometer test

Pre-repair Scan Result

Diagnostic Summary

Scanned Systems	9	Total number of DTC	2
Systems with DTC	2		
Systems with No DTC	5		

Systems with DTC

IC(Instrument Cluster)		1 Faults
U042092	Invalid Data Received From (PSCM)	Not Present

Without SKE		1 Faults
U042092	Invalid Data Received From (PSCM)	Not Present

Systems with No DTC

PCM(Powertrain Control Module)
ABS(Anti-Lock Brake System)
EPS(Electronic-Controlled Power Steering)
BCM/GEM(Body Control Module/Generic Electronic Module)
RCM(Restraint Control Module)

System does not support DTC reading

PATS(Passive anti theft system)-Beta
PATS(Passive anti theft system)-Beta

Copy right
G-Scan Oceania

Post-repair Scan Result

Diagnostic Summary

Scanned Systems	10	Total number of DTC	0
Systems with DTC	0		
Systems with No DTC	7		

Systems with No DTC

PCM(Powertrain Control Module)
ABS(Anti-Lock Brake System)
IC(Instrument Cluster)
EPS(Electronic-Controlled Power Steering)
BCM/GEM(Body Control Module/Generic Electronic Module)
RCM(Restraint Control Module)
Without SKE

System does not support DTC reading

PATS(Passive anti theft system)-Beta
PATS(Passive anti theft system)-Beta
PATS(Passive anti theft system)-Beta

Comment

intermittent symptom

Copy right
G-Scan Oceania